



Warranty Flat Rate Time Schedule for Cox Ride-on Mowers

The following time schedule is to be used in Conjunction with Section 5 of the Cox Industries Limited Warranty Policy.
Cox Industries will, from time to time, update flat rate times, whenever necessary.
Labour rate \$60.00 Inc GST per hour.



Code	Description	Stockman 4500	Stockman 4000	Lawnboss	Cruiser
G1	Customer Service & Relations	0.2	0.2	0.2	0.2
G2	Fault Diagnosis & Test	0.2	0.2	0.2	0.2
G3	Replace Cutter Disc	0.5	0.5	0.5	0.5
G4	Replace Cutter Belt Guides	N/A	0.2	0.2	N/A
G5	Replace Cutter Roller	0.2	0.2	N/A	0.2
G6	Replace Cutter Brake Pad	N/A	0.2	0.2	N/A
G7	Replace Cutter Pulley	0.5	0.5	0.5	0.5
G8	Replace Cutter Shaft	0.8	0.5	0.5	1
G9	Replace Cutter Bearings	1.2	1	1	1.5
G10	Alignment of Clutch Arm Assy & Dress Clutch Cone	0.3	0.3	N/A	N/A
G11	Replace Clutch Shaft, Align & Dress Clutch Cone	0.9	0.9	N/A	N/A
G12	Replace Clutch Pulley, Align & Drss Clutch Cone	0.9	0.9	N/A	N/A
G13	Replace Clutch Cone, Align & Dress Clutch Cone	0.9	0.3	N/A	N/A
G14	Replace Clutch Bearings, Align & Dress Clutch Cone	0.9	0.9	N/A	N/A
G15	Replace Clutch Plate, Align & Dress Clutch Cone	1	1	N/A	N/A
G16	Replace Intershaft, Align & Dress Clutch Cone	1	1	N/A	N/A
G17	Replace Intershaft, Bearings Flanges, Align & Dress Clutch Cone	1	1	N/A	N/A
G18	Replace Intershaft Bearings, Align & Dress Clutch Cone	1	1	N/A	N/A
G19	Replace Brake Band	1	0.5	N/A	N/A
G20	Replace Drive Chain	0.2	0.2	N/A	N/A
G21	Replace Chain Adj. Bearings	0.3	0.3	N/A	N/A
G22	Replace Rear Axle (Hydrostatic Drive).	1	1	1	1
G23	Replace Front Wheel Hub	0.3	0.3	0.3	0.3
G24	Replace Rear Wheel Hub	0.3	0.3	0.3	0.3
G25	Replace Cutter Belt	0.5	0.5	0.5	0.5
G26	Replace Drive Belt	0.5	0.6	0.5	1
G28	Replace Engine Pulley	0.4	0.4	0.4	0.6

G29	Replace Steering Wheel (Control Levers)	0.2	0.2	0.2	0.2
G30	Replace Steering Shaft Upper	0.5	0.5	0.5	N/A
G31	Replace Steering Universal	0.5	0.5	0.5	N/A
G32	Replace Steering Bush Upper	0.5	0.5	0.5	N/A
G33	Replace Steering Shaft Lower	0.8	0.8	0.8	N/A
G34	Replace Steering Bushes Lower	1.5	0.8	0.8	N/A
G35	Unusual failure explain reason in BOX 12				
G36	Replace Drive Cushion	N/A	N/A	0.5	N/A
G37	Replace Drive Pulley	N/A	N/A	0.5	0.5
	Use G35 for all SuperChipper warranty failures				
	ELECTRICAL				
Code	Description	Stockman 4500	Stockman 4000	Lawnboss	Cruiser
E1	Customer Service & Relations	0.2	0.2	0.2	0.2
E2	Circuit Diagnosis & Tests	0.4	0.4	0.4	0.4
E3	Replace Ignition Switch	0.3	0.5	0.3	0.3
E4	Replace Microswitch	0.2	0.2	0.2	0.3
E5	Replace Hourmeter	0.2	N/A	N/A	0.2
E6	Replace Seat Switch	0.3	0.3	0.3	0.3
E7	Replace Light Switch	0.3	N/A	N/A	N/A
E8	Replace Head Light	0.5	N/A	N/A	N/A
E9	Replace PTO Clutch Switch	0.2	N/A	N/A	0.2
E10	Replace Oil Pressure Light	N/A	N/A	N/A	N/A
E12	Replace Fuse	0.1	0.1	0.1	0.3
E13	Replace Solenoid	0.3	0.5	0.3	0.3
E14	Replace Battery	0.2	0.2	0.2	0.2
E15	Replace Wiring Harness	1	1	1	1.5
E16	Replace Electrical PTO Clutch	0.5	N/A	N/A	0.5
E17	Unusual time explain reason in BOX 12 for consideration				